

BRIDGE INSPECTION REPORT

Status: Released

Printed On: 7/14/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

ABK
Inspector's Signature ABK

Cert # G1220 Cert Exp Date 1/12/2022

LAW
Co-Inspector's Signature LAW

Inspections Performed

Report Type	Inspection Type	Date	Freq	Hours	Inspector	Cert No	Co-Insp.
Underwater		4/27/2021	48	3.0	RMP	G1215	JRWH
Condition		4/27/2021	24	1.5	ABK	G1220	LAW

<table style="width: 100%;"> <tr><td><input type="checkbox"/> Alignment (1661)</td><td style="width: 5%; text-align: center;">17</td><td><input type="checkbox"/> Operating Tons (1552)</td></tr> <tr><td><input type="checkbox"/> Deck Overall (1663)</td><td></td><td><input type="checkbox"/> Op RF (1553)</td></tr> <tr><td><input type="checkbox"/> Superstructure (1671)</td><td style="text-align: center;">10</td><td><input type="checkbox"/> Inventory Tons (1555)</td></tr> <tr><td><input type="checkbox"/> Substructure (1676)</td><td></td><td><input type="checkbox"/> Inv RF (1556)</td></tr> <tr><td><input type="checkbox"/> Culvert (1678)</td><td></td><td><input type="checkbox"/> Operating Level (1660)</td></tr> <tr><td><input type="checkbox"/> Chan/Protection (1677)</td><td></td><td><input type="checkbox"/> Open/Closed (1293)</td></tr> <tr><td><input type="checkbox"/> Pier/Abut/Prot (1679)</td><td></td><td><input type="checkbox"/> Structural Eval (1657)</td></tr> <tr><td><input type="checkbox"/> Waterway (1662)</td><td style="text-align: center;">9</td><td><input type="checkbox"/> Deck Geometry (1658)</td></tr> <tr><td><input type="checkbox"/> Scour (1680)</td><td style="text-align: center;">9</td><td><input type="checkbox"/> Underclearance (1659)</td></tr> </table>	<input type="checkbox"/> Alignment (1661)	17	<input type="checkbox"/> Operating Tons (1552)	<input type="checkbox"/> Deck Overall (1663)		<input type="checkbox"/> Op RF (1553)	<input type="checkbox"/> Superstructure (1671)	10	<input type="checkbox"/> Inventory Tons (1555)	<input type="checkbox"/> Substructure (1676)		<input type="checkbox"/> Inv RF (1556)	<input type="checkbox"/> Culvert (1678)		<input type="checkbox"/> Operating Level (1660)	<input type="checkbox"/> Chan/Protection (1677)		<input type="checkbox"/> Open/Closed (1293)	<input type="checkbox"/> Pier/Abut/Prot (1679)		<input type="checkbox"/> Structural Eval (1657)	<input type="checkbox"/> Waterway (1662)	9	<input type="checkbox"/> Deck Geometry (1658)	<input type="checkbox"/> Scour (1680)	9	<input type="checkbox"/> Underclearance (1659)	<table style="width: 100%;"> <tr><td><input type="checkbox"/> Bridge Rails (1684)</td></tr> <tr><td><input type="checkbox"/> Transition (1685)</td></tr> <tr><td><input type="checkbox"/> Guardrails (1686)</td></tr> <tr><td><input type="checkbox"/> Terminals (1687)</td></tr> <tr><td><input type="checkbox"/> Bridge Rail Ht (2612)</td></tr> <tr><td><input type="checkbox"/> Design Curb Ht (2611)</td></tr> </table>	<input type="checkbox"/> Bridge Rails (1684)	<input type="checkbox"/> Transition (1685)	<input type="checkbox"/> Guardrails (1686)	<input type="checkbox"/> Terminals (1687)	<input type="checkbox"/> Bridge Rail Ht (2612)	<input type="checkbox"/> Design Curb Ht (2611)	<table style="width: 100%;"> <tr><td><input type="checkbox"/> No Utilities (2675)</td></tr> <tr><td><input type="checkbox"/> Asphalt Depth (2610)</td></tr> <tr><td>1998 <input type="checkbox"/> Year Built (1332)</td></tr> <tr><td>0 <input type="checkbox"/> Year Rebuilt (1336)</td></tr> </table>	<input type="checkbox"/> No Utilities (2675)	<input type="checkbox"/> Asphalt Depth (2610)	1998 <input type="checkbox"/> Year Built (1332)	0 <input type="checkbox"/> Year Rebuilt (1336)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">NBIS Risk Category</td></tr> <tr><td style="text-align: center;">Routine: No Risk Category</td></tr> <tr><td style="text-align: center;">Underwater: No Risk Category</td></tr> </table>	NBIS Risk Category	Routine: No Risk Category	Underwater: No Risk Category
<input type="checkbox"/> Alignment (1661)	17	<input type="checkbox"/> Operating Tons (1552)																																									
<input type="checkbox"/> Deck Overall (1663)		<input type="checkbox"/> Op RF (1553)																																									
<input type="checkbox"/> Superstructure (1671)	10	<input type="checkbox"/> Inventory Tons (1555)																																									
<input type="checkbox"/> Substructure (1676)		<input type="checkbox"/> Inv RF (1556)																																									
<input type="checkbox"/> Culvert (1678)		<input type="checkbox"/> Operating Level (1660)																																									
<input type="checkbox"/> Chan/Protection (1677)		<input type="checkbox"/> Open/Closed (1293)																																									
<input type="checkbox"/> Pier/Abut/Prot (1679)		<input type="checkbox"/> Structural Eval (1657)																																									
<input type="checkbox"/> Waterway (1662)	9	<input type="checkbox"/> Deck Geometry (1658)																																									
<input type="checkbox"/> Scour (1680)	9	<input type="checkbox"/> Underclearance (1659)																																									
<input type="checkbox"/> Bridge Rails (1684)																																											
<input type="checkbox"/> Transition (1685)																																											
<input type="checkbox"/> Guardrails (1686)																																											
<input type="checkbox"/> Terminals (1687)																																											
<input type="checkbox"/> Bridge Rail Ht (2612)																																											
<input type="checkbox"/> Design Curb Ht (2611)																																											
<input type="checkbox"/> No Utilities (2675)																																											
<input type="checkbox"/> Asphalt Depth (2610)																																											
1998 <input type="checkbox"/> Year Built (1332)																																											
0 <input type="checkbox"/> Year Rebuilt (1336)																																											
NBIS Risk Category																																											
Routine: No Risk Category																																											
Underwater: No Risk Category																																											

Inspection Flags

<input type="checkbox"/> Soundings (2693)	<input type="checkbox"/> Measure Clearance (2694)	<input type="checkbox"/> Revise Rating (2688)	<input type="checkbox"/> Photos (2691)	<input type="checkbox"/> QA Flag (2695)
---	---	---	--	---

BMS Elements

Element	Element Description	Total	Units	CS 1	CS 2	CS 3	CS 4
8112	Timber Sawn Girder	750	LF	736	10	4	0
8361	Scour	2	EA	2	0	0	0
8390	Fixed Bearing	2	EA	2	0	0	0
8391	Moveable Bearing (roller, sliding, etc.)	2	EA	2	0	0	0
8408	Steel Sliding Plate Joint	8	LF	8	0	0	0
8640	Moveable Pedestrian Gangplank	50	LF	50	0	0	0
8701	Ferry Concrete Floating Pontoon	42	CELL	34	7	1	0
8703	Spud Piling & Wells	37	EA	16	0	10	11
8818	Other Pedestrian Railing	630	LF	510	0	0	120
8902	Protective Coating - Piling	7400	SF	6525	200	675	0
8910	Safety Access Ladders	2	EA	2	0	0	0

Notes

--

BRIDGE INSPECTION REPORT

Status: Released

Printed On: 7/14/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK
Carrying		Route On
Intersecting STILL HARBOR (P. SOUND)		Route Under
		Mile Post
		Mile Post

Notes (Continued)

0 ORIENTATION:

The McNeil Island Still Harbor Dock includes the concrete floats, gangplank, and the steel spud piles.
 For location reference: Offshore is north, shore is south, left side is west, and right side is east. Defects on piles are called out in clock direction where 6:00 is facing onshore and 12:00 is offshore.
 See the attached Layout drawing for reference and Pile Inspection Data spreadsheet for additional findings.

9 The WSDOT Bridge Preservation Dive Team performed an underwater inspection of the subject facility on April 27, 2021. A total of 37 steel pipe piles were inspected by diving. The concrete pontoon exteriors were given a cursory swim-by inspection.

In general, the steel pipe piles that position the floating docks (spud piles) are in poor condition. The zinc paint coating on the piles is failing in large areas from the splash zone down to mudline. Missing areas of coating have exposed the steel substrate which now has large areas of surface corrosion and section loss. The overall pitting of the metal made it difficult to obtain accurate thickness readings with the ultrasonic thickness meter. Some pits are to full thickness and plans indicate a 0.5" nominal wall thickness. Twenty-one of the thirty-seven steel spud piles (56%) have holes in them. Thirteen of those piles' holes were caused by constant mechanical abrasion of several UHMW "log" booms tethered to the piles. Eleven of those piles may have enough damage to threaten performance during extreme events. These holes have increased in size and number since the previous underwater inspection. The concrete floating pontoons had thick marine growth covering nearly 100% of the surface area. Spot cleaning revealed no defects.

Repair or replace steel spud/guide piles that are rated as Condition State 4 with multiple and large holes. REPAIR #10003.

Recommend retaining the 48-month frequency for underwater inspections.

1676 SUBSTRUCTURE:

Substructure coded to '4' due to holes in more than half of the steel piling.

1677 CHANNEL:

This structure abuts another structure and does not connect to the shoreline directly. No bank issues noted. No restrictions to water flow past the structure.

1680 SCOUR:

Structure is in tidal waters with weak and variable tidal currents. Scour code set to "T - tidal" and is considered a low risk for scour. See Note 8361.

8112 TIMBER SAWN GIRDER:

The floating dock concrete segments are held together with timber walers side mounted and through bolted. These provide a fairly rigid connection between the docks and provide a rub face for docked vessels. Winter storms have caused breakage of the timber walers.
 Joint between panels E & F to be uneven up to 1" (photo #28).
 Joint connecting Pontoons F and G has been built up with a horizontal stiffening plate and steel channels in addition to replacing the timber walers (photo #26) (CS 2).
 The last four feet of timber waler near Spud Pile A is broken (photo #34).
 Many of the timber waler through bolts have been replaced. There are still some missing near Piles U and V (photo #33).
 Eyelets securing log fenders are distressed and bent (photo #35). REPAIR #10004.
 See the attached layout and photos for more details.

8361 SCOUR (Field):

There are two lines of spud/guide piles, 1 - 12 and A - Y. Assume each line is a bent or pier.

Underwater Inspection Findings:
 Water flow in the vicinity is tidal. No scour patterns or scour countermeasures were observed.

See attached Layout drawing for details.

8390 FIXED BEARING:

Fixed bearings located at top gangplank connection to the concrete pier (photo #10).

8391 MOVEABLE BEARING:

Slider bearings located at the gangplank landing (photo #11).

BRIDGE INSPECTION REPORT

Status: Released

Printed On: 7/14/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK
Carrying		Route On
Intersecting STILL HARBOR (P. SOUND)		Route Under
		Mile Post
		Mile Post

Notes (Continued)

8408 **STEEL SLIDING PLATE JOINT:**
Steel sliding joint at the top of the gangplank (element 8390, photo #10) Steel plate at the Pontoon T has been removed and no longer coded (photo #36).

8701 **CONCRETE FLOATING PONTOON:**
A repair to the pontoon timber walers tying the adjoining floats together was done in 2016 - 2017. Prior to the repair, the listing of the pontoon segments indicates the pontoon polystyrene has degraded and taken on water through the waler bolt holes. There is a serviceability issue which may reappear after a significant storm from the north.
Dock lists downward 4" from Panel C to the end of Panel A (Photo #29).
At the M-N joint shore side, the boat tie off cleat is bolted only to the timber walers (Photo #30).
The U-V joint has a 2.5' x 9" x 1" deep spall (Photo #32) (CS 3).
Seven of the dock segments have been repaired since the 2013 inspection (CS 2).

Underwater Inspection Findings:
The submerged surfaces of the pontoons are covered in heavy marine growth, making a detailed inspection very difficult. Spot cleaning revealed no defects (Photo #UW-1).

See attached Layout drawing for locations and details.

8703 **SPUD PILING & WELLS:**
There are thirty-seven spud piles; Piles 1 through 12 on the longitudinal (onshore to offshore) bent and Piles A through Y on the transverse (left to right) bent. Spud pile rollers are all intact, some are bent from storm events (Photo #27).

Underwater Inspection Findings:
The spud piles, also referred to as "guide piles", position the floats and are in generally poor condition underwater. The coating has generally failed from the intertidal zone (ITZ) down to mudline, exposing the steel underneath (Photo #UW-2). These exposed areas have surface corrosion with pitting and section losses of up to full thickness (holes) in localized areas (plans indicate 0.5" nominal wall thickness). Moderate marine growth is present but attempts to clean for inspection also removed any coating left as well. Twenty-one of the spud piling (56%) have holed through in the lower ITZ due to either mechanical abrasion damage from the UHMW plastic "log" booms that contact the piles (Photos #UW-3 thru #UW-7 and #UW-10 thru #UW-24) or from pitting that has rusted through. The 2017 underwater inspection counted only 12 spud piles with holes (32%). These holes have grown significantly larger in size since the previous underwater inspection and new holes were observed where only flat spots were seen before.

Eleven spud piles (Piles A, D, E, F, J, L, O, P, V, W, and Y) have section loss that threatens performance during an extreme event such as high winds and heavy wave action.
(Photos #UW-10 through #UW-24)(CS4). REPAIR #10003.

Ten spud piles (Piles 5, 9, 10, B, C, G, H, K, M, and S) have section loss, but do not currently threaten the performance of the pontoon positioning system (Photo #UW-2).

See attached Layout drawing and Pile Data spreadsheet for detailed defect descriptions and locations.

8818 **OTHER PEDESTRIAN RAILING:**
The steel post stanchions and rope rail have been removed from floats T thru Y prior to the 2017 inspection (photo #25).

8902 **INORGANIC ZINC VINYL PAINT:**
Many of the spud piles have rust blisters and seam rust (photo #37).

Underwater Inspection Findings:
Much of the spud pile coating has failed underwater. Pile metal substrate is exposed between 10% and 50% of the pile surface area underwater, see Element 8703 Photos #UW-2 and #UW-8 for typical underwater coating condition.

8910 **SAFETY ACCCESS LADDERS:**
There is a ladder attached to each end of the t-dock (Photo UW-25).

See attached Layout drawing for locations of ladders.


Underwater		4/27/2021	Lead: RMP		Co: JRWH		
Routine		4/27/2021	Lead: ABK		Co: LAW		
Pile Location			Condition/Damage			Inspection Type	
Bent	Pile	Condition State (CS)	MDL Elev. (MLLW)	Defect Location	Details/Remarks	Routine/UW	Date
PILE INSPECTION DATA - Steel Dock Spud Piles are 14" Diam. and 3/8" Thick							
Pile Defect Locations are called out in Clock Direction with Offshore face at 12:00 and Onshore face at 06:00.							
*All areas of surface rust or coating failure (cf) have localized pitting up to 1/4" deep.							
Longitudinal	1	1		MDL - ITZ	*50% area surface rust / 50% area marine growth	UW	4/27/2021
Onshore to	2	1		MDL	Thickness 0.395" (2013)	UW	4/27/2021
Offshore	3	1		MDL - ITZ	*25% area surface rust / 75% area marine growth coverage	UW	4/27/2021
	4	1	-7.0	MDL	Thickness 0.370" (2013)	UW	4/27/2021
	5	3	-7.0	MDL - ITZ	*25% area surface corrosion with pitting up to 0.25" deep	UW	4/27/2021
	6	1	-8.0	MDL	Thickness 0.375" (2021)	UW	4/27/2021
	7	1	-8.0	MDL - ITZ	*25% area surface rust / 75% area marine growth	UW	4/27/2021
	8	1	-8.5	MDL	*25% area surface rust / 75% area marine growth	UW	4/27/2021
	9	3	-9.5	MDL - ITZ	Thickness 0.375" (2013)	UW	4/27/2021
	10	3	-9.5	MDL - ITZ	*25% area surface rust / 75% area marine growth	UW	4/27/2021
	11	1	-10.0	MDL+5 @5:30	1-1/2" diam. hole	UW	4/27/2021
	12	1	-11.0	MDL	*25% area surface rust / 75% area marine growth	UW	4/27/2021
Transverse (Lt to Rt)	A	4	-13.0	MDL - ITZ	*25% area surface rust / 75% area marine growth	UW	4/27/2021
				MDL	Thickness 0.270" in localized deep pit (2013)		
				MDL+5 to +7 @6:00	3"(W) x 36"(H) hole from mechanical abrasion of log boom (2017 Photo #UW-3, 2021 Photo #UW-10)		
				MDL+7 @6:00	1-1/2" diam. hole		
				MDL+5 to +7 @6:00	6"(W) very thin area (not holed thru) with heavy pitting		



Underwater Routine		4/27/2021	Lead: RMP		Co: JRWH		
Pile Location		4/27/2021	Lead: ABK		Co: LAW		
Pile Location		Condition/Damage				Inspection Type	
Bent	Pile	Condition State (CS)	MDL Elev. (MLLW)	Defect Location	Details/Remarks	Routine/UW	Date
	B	3	-13.0	MDL - ITZ MDL+5 @4:30 MDL+3 @5:00 MDL	*50% area surface rust / 50% area marine growth 1" diam. hole 2"(W) x 2"(H) hole	UW	4/27/2021
	C	3	-13.0	MDL - ITZ MDL+10 to +12 MDL +11 @6:00 MDL +5 MDL	*50% area surface rust / 50% area marine growth 4" wide flat spot from mechanical abrasion of log boom 1-1/2" diam. star pattern hole in the 4" wide flat spot 1-1/2" diam. hole	UW	4/27/2021
	D	4	-13.5	MDL+9 to +12 @6:00 MDL+9 MDL+8.5 @6:00 MDL+8 MDL - ITZ MDL+2 @2:00 MDL+1.5 @12:00 MDL	4"(W) x 36"(H) hole from mechanical abrasion of log boom (Photo #UW-11) 3"(W) x 12"(H) hole from mechanical abrasion of log boom 1-1/2" diam. hole 1" dia. hole from mechanical abrasion of log boom *50% area surface rust / 50% area marine growth 2"(W) x 1"(H) hole 5"(W) x 2"(H) hole (Photo #UW-12)	UW	4/27/2021
	E	4	-14.0	MDL+10.5 to +12 @6:00 MDL+9 MDL+8 to +12 MDL - ITZ MDL+2 @12:00-3:00 MDL+1.5 @3:00 MDL	2"(W) x 18"(H) hole from mechanical abrasion of log boom (Photos #UW-13 and #UW-14) 1/2" diam. hole from mechanical abrasion of log boom 4" wide flat spot from mechanical abrasion of log boom *25% area surface rust / 75% area marine growth 4-1/2"(W) x 1-1/2"(H) and 3-1/2"(W) x 3/4"(H) (Photo #UW-15) 2" diam. hole	UW	4/27/2021
	F	4	-13.5	MDL+10to+8.5@6:00 MDL+9@6:00 MDL+8.5@6:00 MDL - ITZ MDL	3-1/2"(W) x 18"(H) hole from mechanical abrasion of log boom (Photos #UW-16 and #UW-17) 2"(W) x 2-1/2"(H) hole from mechanical abrasion of log boom 1-1/2"(W) x 3"(H) hole from mechanical abrasion of log boom *25% area surface rust / 75% area marine growth	UW	4/27/2021

Underwater		4/27/2021	Lead: RMP		Co: JRWH		
Routine		4/27/2021	Lead: ABK		Co: LAW		
Pile Location		Condition/Damage				Inspection Type	
Bent	Pile	Condition State (CS)	MDL Elev. (MLLW)	Defect Location	Details/Remarks	Routine/UW	Date
	G	3		MDL+9.5to+11.5 MDL+6@6:00 MDL+1.5@12:00 MDL - ITZ MDI	3"(W) x 2"(H) flat area from mechanical abrasion of log boom, no holes 1/2" diam. hole in pit 1/4" diam. hole in pit *25% area surface rust / 75% area marine growth	UW	4/27/2021
	H	3	-14.0	MDL+4@12:00 MDL+3.5@11:00 MDL+2@12:00 MDL+6" @11:00 MDL - ITZ MDI	1" diam. hole 3" diam. hole 3"(W) x 2"(H) hole 2" diam. hole *25% area surface rust / 75% area marine growth	UW	4/27/2021
	I	1	-14.0 -13.5	MDL - ITZ MDL	*25% area surface rust / 75% area marine growth	UW	4/27/2021
	J	4		MDL+11 MDL+7 to +8.5@6:00 MDL+7 to +11 MDL+4@11:00 MDL+3.5@12:00 MDL+2@12:00 MDL - ITZ MDI	12"(H) x 2.5"(W) hole from mechanical abrasion of log boom [Photos #UW-4 (2013) and #UW-5 (2017)] 3"(W) x 18"(H) hole from mechanical abrasion of log boom (Photo #UW-18) 4" wide flat spot from mechanical abrasion of log boom 1-1/2" diam. hole 1-1/2"(W) x 2"(H) hole 3-1/2"(W) x 1"(H) hole *25% area surface rust / 75% area marine growth	UW	4/27/2021
	K	3	-13.0 -12.0	MDL+7to+10 @6:00 MDL - ITZ MDL	4" wide flat spot from mechanical abrasion of log boom, thin no holes *25% area surface rust / 75% area marine growth	UW	4/27/2021
	L	4	-12.5	MDL+9 @6:00 MDL+8 @6:00 MDL+6 - ITZ MDL+4 @12:00 MDL - ITZ MDI	3"(W) x 24"(H) hole from mech abrasion of log boom (Photo #UW-19) 1" diam. hole 5" wide flat spot from mech abrasion of log boom 3"(W) x 2"(H) hole *25% area surface rust / 75% area marine growth	UW	4/27/2021

Underwater		4/27/2021	Lead: RMP				Co: JRWH	
Routine		4/27/2021	Lead: ABK				Co: LAW	
Pile Location		Condition/Damage					Inspection Type	
Bent	Pile	Condition State (CS)	MDL Elev. (MLLW)	Defect Location	Details/Remarks	Routine/UW	Date	
	M	3		MDL+9 @6:00 MDL+8 @6:00 MDL+8-ITZ MDL-ITZ	2"(W) x 3"(H) hole from mechanical abrasion of log boom 2-1/2"(W) x 7"(H) hole from mechanical abrasion of log boom 3" - 4" wide flat spot from mechanical damage of log boom *25% area surface rust / 75% area marine growth	UW	4/27/2021	
	N	1	-11.5	MDI MDL - ITZ	*10% area surface rust / 90% area marine growth (typical).	UW	4/27/2021	
	O	4	-12.0	MDL MDL+6to+8 @6:00	4"(W) x 24"(a9)H hole from mechanical abrasion of log boom (Photos #UW-6 (2017) and Photo #UW-20) 4" wide flat spot from mechanical damage of log boom	UW	4/27/2021	
				MDL+5 to +9 MDL+5 @3:00 MDL+4 @4:00 MDL +8" @3:00 MDL+3" @2:00 MDL - ITZ	1" diam. hole 1/4" diam. hole in pit 1/2" diam. hole 1-1/2"(W) x 1/4"(H) hole *10% area surface rust / 90% area marine growth			
	P	4	-11.0	MDI MDL+4to+8.5 @6:00 MDL+3.5 @6:00 MDL - ITZ	5"(W) x 54"(H) large hole from mechanical abrasion of log boom (Photo #UW-7 and #UW-21) 2" diam. hole *25% area surface rust / 75% area marine growth	UW	4/27/2021	
	Q	1	-10.5	MDI MDL - ITZ	*25% area surface rust / 75% area marine growth	UW	4/27/2021	
	R	1	-11.0	MDL				
				MDL - ITZ MDL	*25% area surface rust / 75% area marine growth	UW	4/27/2021	
	S	3	-11.0	MDL+5 @1:00 MDL+3 @12:30 MDL+1 @12:30 MDL - ITZ	2"(W) x 1"(H) and 1" diam. Hole 2"(W) x 3"(H) hole 2-1/2"(W) x 6"(H) hole *25% area surface rust / 75% area marine growth, Photo #UW-2 shows typical pile condition underwater	UW	4/27/2021	
				MDL				
	T	1	-10.5	MDL - ITZ MDL	*25% area surface rust / 75% area marine growth	UW	4/27/2021	



PLAN

LEGEND:

- VERTICAL ROUND STEEL PILE
- STEEL PILE w/ MODERATE HOLED THROUGH SECTION LOSS (CS3)
- ◻ STEEL CHANNEL WALER REPAIR
- ⌵ LADDER
- ① STEEL PILE w/ EXCESSIVE HOLED THROUGH SECTION LOSS (CS4)

ROUTINE INSPECTION	UNDERWATER INSPECTION
Date: 4/27/2021	Date: 4/27/2021
Scale: 1"=25'	Scale: 1"=25'
Inspected by: ABK/LAW	Inspected by: RMP/JRW

WSDOT
BRIDGE PRESERVATION
OFFICE

Washington State
Department of Transportation
Bridge and Structures Office

DOC - 6
MCNEIL ISLAND STILL HARBOR DOCK
SID#00200441

LAYOUT

BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-31

0 Orientation

Photo Type: G - General

Orientation: Shore

Date: 4/8/2019

Repairs:

Gangplank to floating pontoons.



SI-2

0 Orientation

Photo Type: E - Elevation

Orientation: Sea

Date: 5/23/2013

Repairs:

Still Harbor Elevation from Shore.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-9

0 Orientation

Photo Type: W - UW Cover

Orientation: Left

Date: 4/27/2021

Repairs:

McNeil Island Still Harbor Dock looking inshore left.



UW-0

9 Underwater Report Executive Summary


Photo Type: W - UW Cover

Orientation: Shore

Date: 4/27/2017

Repairs:

Elevation for UW cover.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-28

8112 Timber Sawn Girder


Photo Type: G - General

Orientation: Right

Date: 4/8/2019

Repairs:

Top surface of joint between panels E & F is uneven up to 1".



SI-26

8112 Timber Sawn Girder

Photo Type: G - General

Orientation: Left

Date: 4/26/2017

Repairs:

Joint connecting pontoons F and G has been built up with stiffening plate and steel channels have been added in addition to replacing the timber walers.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting . STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-34

8112 Timber Sawn Girder

Photo Type: G - General

Orientation: Sea

Date: 4/27/2021

Repairs:

Near Spud Pile A, the last four feet of the timber waler are broken.



SI-33

8112 Timber Sawn Girder

Photo Type: G - General

Orientation: Sea

Date: 4/27/2021

Repairs:

Many of the through bolts holding the timber walers have been replaced. Some are still missing in several pontoon segments.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-35

8112 Timber Sawn Girder

Photo Type: R - Repair

Orientation: Shore

Date: 4/27/2021

Repairs: 10004

Eyebolts securing log fenders are distressed and bent.



SI-10

8390 Fixed Bearing

Photo Type: G - General

Orientation: Sea

Date: 5/23/2013

Repairs:

Fixed bearings located at top of gangplank connection to the concrete pier.



Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-11

8391 Moveable Bearing (roller, sliding, etc.)

Photo Type: G - General

Orientation: Sea

Date: 5/23/2013

Repairs:

Slider bearings located at the gangplank landing.



SI-36

8408 Steel Sliding Plate Joint

Photo Type: G - General

Orientation: Right

Date: 4/27/2021

Repairs:

Steel plate joint has been replaced with rubber mat.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-29

8701 Ferry Concrete Floating Pontoon

Photo Type: G - General

Orientation: Sea

Date: 4/8/2019

Repairs:

Dock lists 4" down from Panel C to the end of Panel A.



SI-30

8701 Ferry Concrete Floating Pontoon


Photo Type: G - General

Orientation: DN

Date: 4/8/2019

Repairs:

At the M-N joint shore side, the boat tie off cleat is bolted only to the timber walers.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-32

8701 Ferry Concrete Floating Pontoon

Photo Type: G - General

Orientation: Left

Date: 4/27/2021

Repairs:

The U-V joint has a 2.5" x 9" x 1" deep spall.



UW-1

8701 Ferry Concrete Floating Pontoon

Photo Type: G - General

Orientation:

Date: 5/23/2013

Repairs:

Typical heavy marine growth on floating dock sections.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-27

8703 Spud Piling & Wells

Photo Type: G - General

Orientation:

Date: 4/26/2017

Repairs:

Spud pile rollers are all intact, some are bent from storm events.



UW-2

8703 Spud Piling & Wells

Photo Type: M - Monitor

Orientation:

Date: 5/23/2013

Repairs:

T-dock Pile S; general coating failure and rusting with section loss. Typical of T-dock piles.



Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-3

8703 Spud Piling & Wells

Photo Type: I - In Depth

Orientation:

Date: 4/27/2017

Repairs:

T-dock, Pile A: 18" H x 4" W hole from mechanical damage.



UW-4

8703 Spud Piling & Wells

Photo Type: I - In Depth

Orientation:

Date: 5/23/2013

Repairs:

T-dock Pile J; 4" wide mechanical damage (flat spot). 2013 photo; compare to UW-5 for 2017 photo and UW-18 for 2021 photo to see progression.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-5

8703 Spud Piling & Wells

Photo Type: I - In Depth

Orientation:

Date: 4/27/2017

Repairs:

T-dock Pile J: 12" H x 2.5" W hole (was just a flat spot in 2013, see UW-4).



UW-6

8703 Spud Piling & Wells

Photo Type: I - In Depth

Orientation:

Date: 4/27/2017

Repairs:

T-dock Pile O: 18" H x 4" W (up to) hole from mechanical damage.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK	
Carrying		Route On	Mile Post
Intersecting STILL HARBOR (P. SOUND)		Route Under	Mile Post

UW-7

8703 Spud Piling & Wells
Photo Type: I - In Depth
Orientation:
Date: 4/27/2017
Repairs:
T-dock Pile P: Large 3-ft. vertical hole from mechanical damage.



UW-10

8703 Spud Piling & Wells
Photo Type: R - Repair
Orientation: Sea
Date: 4/27/2021
Repairs: 10003
Pile A has a 3"(W) x 36"(H) hole from mechanical abrasion of UHMW log boom.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK	
Carrying		Route On	Mile Post
Intersecting STILL HARBOR (P. SOUND)		Route Under	Mile Post

UW-11

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile D has a 4"(W) x 36"(H) hole from mechanical abrasion of UHMW log boom.



UW-12

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Shore

Date: 4/27/2021

Repairs: 10003

Pile D has a 5"(W) x 2"(H) hole.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-13

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: DN

Date: 4/27/2021

Repairs: 10003

Pile E has a 2"(W) x 18"(H) hole from mechanical abrasion of log boom. Looking offshore during low tide.



UW-14

8703 Spud Piling & Wells


Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile E has a 2"(W) x 18"(H) hole from mechanical abrasion of log boom looking offshore.



BRIDGE INSPECTION REPORT

Status: Released
CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Printed On: 8/5/2021
Release Date: 7/14/2021

Agency: Other State Agencies
Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK	
Carrying		Route On	Mile Post
Intersecting STILL HARBOR (P. SOUND)		Route Under	Mile Post

UW-15

8703 Spud Piling & Wells

Photo Type: R - Repair
Orientation: Shore
Date: 4/27/2021
Repairs: 10003

Pile E has 4-1/2"(W) x 1-1/2"(H) and 3-1/2"(W) x 3/4"(H) side-by-side holes looking inshore left.




UW-16

8703 Spud Piling & Wells

Photo Type: R - Repair
Orientation: Sea
Date: 4/27/2021
Repairs: 10003

Pile F has 3-1/2"(W) x 18"(H), 2"(W) x 2-1/2"(H), and 1-1/2"(W) x 3"(H) holes from mechanical abrasion of log boom at low tide.



Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK	
Carrying		Route On	Mile Post
Intersecting STILL HARBOR (P. SOUND)		Route Under	Mile Post

UW-17

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: DN

Date: 4/27/2021

Repairs: 10003

Pile F has 3-1/2"(W) x 18"(H), 2"(W) x 2-1/2"(H), and 1-1/2"(W) x 3"(H) holes from mechanical abrasion of log boom.



UW-18

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile J has a 3"(W) x 18"(H) hole from mechanical abrasion of log boom.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-19

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile L has a 3"(W) x 24"(H) hole from mech abrasion of log boom.



UW-20

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile O has a 4"(W) x 24"(H) hole from mechanical abrasion of log boom.



Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-21

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile P has a 5"(W) x 54"(H) large hole from mechanical abrasion of log boom.



UW-22

8703 Spud Piling & Wells

Photo Type: R - Repair

Orientation: Sea

Date: 4/27/2021

Repairs: 10003

Pile V has 4" (W) x 24"(H) and 3"(W) x 14"(H) holes from mechanical abrasion of log boom.



BRIDGE INSPECTION REPORT

Status: Released
CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Printed On: 8/5/2021
Release Date: 7/14/2021

Agency: Other State Agencies
Program Mgr: Evan M Grimm

Br. No. DOC-6	SID 00200441	Br. Name MCNEIL IS. STILL HARBOR DOCK	
Carrying		Route On	Mile Post
Intersecting STILL HARBOR (P. SOUND)		Route Under	Mile Post

UW-23

8703 Spud Piling & Wells

Photo Type: R - Repair
Orientation: Sea
Date: 4/27/2021
Repairs: 10003

Pile W has 4-1/2"(W) x 18"(H), 2-1/2"(W) x 7"(H), and 3"(W) x 8"(H) holes from mechanical abrasion of log boom.



UW-24

8703 Spud Piling & Wells

Photo Type: R - Repair
Orientation: Sea
Date: 4/27/2021
Repairs: 10003

Pile Y has a 3"(W) x 18"(H) hole and a 3"(W) x 6"(H) hole from mechanical abrasion of log boom.



BRIDGE INSPECTION REPORT

Status: Released
CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Printed On: 8/5/2021
Release Date: 7/14/2021

Agency: Other State Agencies
Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

SI-25

8818 Other Pedestrian Railing

Photo Type: G - General

Orientation: W

Date: 4/26/2017

Repairs:

The steel post stanchions and rope rail have been removed from floats T thru Y.



SI-37

8902 Inorganic Zinc Vinyl Paint

Photo Type: G - General

Orientation: Right

Date: 4/27/2021

Repairs:

Typical shot of spud piles. Seam rust on welds are breaking through the paint.



BRIDGE INSPECTION REPORT

Status: Released

Printed On: 8/5/2021

Agency: Other State Agencies

CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

Release Date: 7/14/2021

Program Mgr: Evan M Grimm

Br. No. DOC-6

SID 00200441

Br. Name MCNEIL IS. STILL HARBOR DOCK

Carrying

Route On

Mile Post

Intersecting STILL HARBOR (P. SOUND)

Route Under

Mile Post

UW-8

8902 Inorganic Zinc Vinyl Paint

Photo Type: I - In Depth

Orientation:

Date: 4/27/2017

Repairs:

Typical pile condition underwater. Coating has failed over 25%-50% of the surface area on the piles below water. Example of ~25% exposed metal shown.



UW-25

8910 Safety Access Ladders

Photo Type: G - General

Orientation: Left

Date: 4/27/2021

Repairs:

There is a ladder attached to each end of the t-dock.



WASHINGTON STATE DEPARTMENT OF TRANSPORTATION
 NBI STRUCTURE INVENTORY AND APPRAISAL REPORT
 (ENGLISH UNITS)

CD Date: 6/29/2021 Printed on: 7/14/2021
 CD Guid: e6d3761d-7a52-4345-8cc3-ba9e7bb81861

IDENTIFICATION		WSBIS DATA	
(1) STATE NAME - WASHINGTON	530	BRIDGE NUMBER	DOC-6
(8) STRUCTURE NUMBER	# 002004410000000	BRIDGE NAME	MCNEIL IS. STILL HARBOR DOCK
(5) INVENTORY ROUTE (ON/UNDER) - Under	0 8 0 10210	CUSTODIAN	Other State Agencies
STATE ROUTE MILEPOST	5.96	CROSSING DESC	
(2) HIGHWAY AGENCY DISTRICT -		MAIN LISTING FLAG	M
(3) COUNTY CODE 53 - Pierce County	(4) PLACE CODE 00000	SUFFICIENCY RATING	
(6) FEATURES INTERSECTED	STILL HARBOR (P. SOUND)	CLASSIFICATION	
(7) FACILITY CARRIED		(112) NBIS BRIDGE LENGTH	
(9) LOCATION	MCNEIL ISLAND	(104) HIGHWAY SYSTEM - Not on the NHS	0
(12) BASE HIGHWAY NETWORK - Not part of network	0	(26) FUNCTIONAL CLASS -	
(13) LRS INV ROUTE AND SUB ROUTE		(100) DEFENSE HIGHWAY - Not a STRAHNET route	0
(11) LRS MILEPOST		(101) PARALLEL STRUCTURE -	
(16) LATITUDE	47 Deg 12 Min 53.69 Sec	(102) DIRECTION OF TRAFFIC -	
(17) LONGITUDE	122 Deg 39 Min 59.14 Sec	(103) TEMPORARY STRUCTURE - Not Applicable	
(98A) BORDER BR. - (98B)	(99) BORDER BR. SID	(105) FEDERAL LANDS HIGHWAY -	
		(110) DESIGNATED NATIONAL NETWORK - Not part of network	0
STRUCTURE TYPE AND MATERIAL		(20) TOLL -	
(43) STRUCTURE TYPE MAIN: MATERIAL -		(21) MAINTENANCE -	
DESIGN -		(22) OWNER -	
(44) STRUCTURE TYPE APPR: MATERIAL -		(37) HISTORICAL SIGNIFICANCE -	
DESIGN -		CONDITION	
(45) NO. OF SPANS IN MAIN UNIT		(58) DECK	
(46) NO. OF APPROACH SPANS		(59) SUPERSTRUCTURE	
(107) DECK STRUCTURE TYPE -		(60) SUBSTRUCTURE	
(108) WEARING SURFACE / PROTECTIVE SYSTEM:		(61) CHANNEL AND CHANNEL PROTECTION	
(A) TYPE OF WEARING SURFACE -		(62) CULVERTS	
(B) TYPE OF MEMBRANE -		LOAD RATING AND POSTING	
(C) TYPE OF DECK PROTECTION -		(31) DESIGN LOAD -	
AGE AND SERVICE		(63) OPER RATING METHOD -	
(27) YEAR BUILT	1998	(64) OPERATING RATING	
(106) YEAR RECONSTRUCTED		(65) INV RATING METHOD -	
(42) TYPE OF SERVICE ON - Other	0	(66) INVENTORY RATING	
UNDER - Other	0	(70) BRIDGE POSTING -	
(28) LANES: ON STRUCTURE 0	UNDER STRUCTURE 0	(41) STRUCT OPEN, POSTED, CLOSED -	
(29) AVERAGE DAILY TRAFFIC	0	APPRAISAL	
(30) YEAR OF ADT	(109) TRUCK ADT 0%	(67) STRUCTURAL EVALUATION	
(19) BYPASS, DETOUR LENGTH	000	(68) DECK GEOMETRY	
GEOMETRIC DATA		(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	
(48) LENGTH OF MAXIMUM SPAN		(71) WATERWAY ADEQUACY	
(49) STRUCTURE LENGTH		(72) APPROACH ROADWAY ALIGNMENT	
(50) CURB OR SIDEWALK: LEFT	RIGHT	(36) TRAFFIC SAFETY FEATURES	
(51) BRIDGE ROADWAY WIDTH CURB TO CURB		(113) SCOUR CRITICAL BRIDGE	
(52) DECK WIDTH OUT TO OUT		PROPOSED IMPROVEMENTS	
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)		(75) TYPE OF WORK -	
(33) BRIDGE MEDIAN -		(76) LENGTH OF STRUCTURE IMPROVEMENT	
(34) SKEW Deg	(35) STRUCTURE FLARED	(94) BRIDGE IMPROVEMENT COST	
(10) INVENTORY ROUTE MIN VERT CLEAR	99 ft 99 in	(95) ROADWAY IMPROVEMENT COST	
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR		(96) TOTAL PROJECT COST	
(53) MIN VERT CLEAR OVER BRIDGE RDW		(97) YEAR OF IMPROVEMENT COST ESTIMATE	
(54) MIN VERT UNDERCLEAR		(114) FUTURE ADT	
(55) MIN LAT UNDERCLEAR RT		(115) YEAR OF FUTURE ADT	
(56) MIN LAT UNDERCLEAR LT		INSPECTIONS	
NAVIGATION DATA		(90) INSPECTION DATE	(91) FREQUENCY MO
(38) NAVIGATION CONTROL -		(92) CRITICAL FEATURE INSPECTION:	(93) CFI DATE
(111) PIER PROTECTION - Not Applicable		(A) FRACTURE CRIT DETAIL - NO -	Month (A) ___/___
(39) NAVIGATION VERTICAL CLEARANCE		(B) UNDERWATER INSP - NO -	Month (B) ___/___
(116) VERT-LIFT BRIDGE NAV MIN VERT CLR		(C) OTHER SPECIAL INSP - NO -	Month (C) ___/___
(40) NAVIGATION HORIZONTAL CLR			