



Office: 888 951 1114 Fax: 888 951 1117

Photographs

Western State (Building 17 - C7, 8, 9)
Lakewood, WA
7/2/2018










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA





C7-103, 109, 123, 104, 110, 116, 136, 142, 135 (Faucet) - Risk H






Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA















Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 3









Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 4








Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

C7-114 (Tub water controls-like kind) - Risk H













Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 6



C7-118 (Medical equipment and cart, Oxygen holder chains and hook, Wall Hook, Cabinet hinges, Sink hardware standard, Electrical conduit, Wall mounted holders and hook) - Risk H








C7-118 Oto scope & Blood Pressure, Paper towel dispenser, View box, Glove holders, Lay in ceiling) - Risk H

















Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 8










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA











Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 10












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 11







Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA





C7-146 Laundry room (Faucet hardware, cabinet hinges) - Risk H




C7-146 (Washer water connections) - Risk H



















Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 15










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA













Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 18










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA






C8-201, 202, 204, 208, 207, 236, 242, 235 (Fire strobe and conduit) - Risk H
















Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA













Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 22










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

























Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 26














Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 27










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 28










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA









Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA













Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 32










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 33






C9- Patio (Water valve cover) - Risk H







C9- Patio (Metal cover) - Risk H



Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 34








C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Vent style 1) - Risk H







C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Vent style 2) - Risk H






Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Door handle-like kind) - Risk H



C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Door opens inward) - Risk H






Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA


Page 36

C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Window top) - Risk H



C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Cabinet hinges-like kind) - Risk H








C9-301, 305, 307, 311, 315, 321, 302, 314, 334, 338, 340, 344, 341, 337, 333 (Bulletin boards-like kind) - Risk H







Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 37











Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 38












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA


Page 39






C9-313, 319, 339, 343, 354, 350 (Lights not tamper proof-like kind) - Risk H








C9-313, 319, 339, 343, 354, 350 (Vents-like kind) - Risk H























Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA


Page 41



C9-314 (Tub hardware) - Risk H












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 42












Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA


















Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA







Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA








Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA









Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

C9-346 (Laundry room: ame as all other laundry rooms: Washer connections, Sink hardware, Cabinet hinges, Lay in ceiling, Window top not covered- like kind) - Risk H










Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 48











Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA













Photographs — 7/2/2018 — Western State (Building 17 - C7, 8, 9) — Lakewood, WA

Page 50

