



Office: 888 951 1114 Fax: 888 951 1117

Photographs


Western State (Building 27 - W1N & W1S)
Lakewood, WA
7/2/2018






































Page 2

























Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA










Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA












Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA












Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA












Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

Page 8

W1N- 153, 145, 135, 131 (Sink Faucets) - Risk H







W1N- 155, 128, 149 (CPAP) - Risk H





Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA










Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA






W1N-134, 132, 130, 128, 126, 124, 122, 155, 149, 147, 143, 139, 133, 129 (Door handle-like kind) - Risk H




W1N-134, 132, 130, 128, 126, 124, 122, 155, 149, 147, 143, 139, 133, 129 (Strike plate-like kind) - Risk H






Page 11










W1N-134, 132, 130, 128, 126, 124, 122, 155, 149, 147, 143, 139, 133, 129 (Door stop-like kind) - Risk H







Page 12









W1N-134, 132, 130, 128, 126, 124, 122, 155, 149, 147, 143, 139, 133, 129 (Nurse call) - Risk H







Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

Page 13













Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

W1S- 120 (TV cabinet lock, latch, front cover hinges, Window tops not covered, Pool table, Foosball table, Treadmill, Door handle standard) - Risk M



W1S- 120 (Treadmill, Pool table, Foosball table, Window tops not covered, TV cabinet lock, latch and front cover hinges, Door handle standard) - Risk H










Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

Page 15









Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

W1S- 142 (Cabinet hinges, Curtain glide mounted with wood across ceiling, Otoscope & Blood Pressure units on wall, Sink hardware standard, Paper towel dispenser, Shelves,) - Risk H








W1S- 150, 154, 160, 164, 168, 170, 176, 171, 169, 167, 165,163, 161 (Door closers) - Risk H






Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA











Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA


Page 18













Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA









Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA











Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

Page 21









Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA

Page 22








































Photographs — 7/2/2018 — Western State (Building 27 - W1N & W1S) — Lakewood, WA